




GRUPPO VITE MOD. V100/B
AIR END MOD. V100/B

8-800-333-23-68


SEZIONE B-B
of 3 holes baseplate connection




Drainage oil from oil separator
 Rp1/4 Thread Depth 15






DETTAGLIO A



Direction of rotation



Rp1/4 Thread Depth 13



TIPO TYPE	PQ	REVISIONE REVISION	00	DATA DATE	01/08	ARTICOLO ARTICLE	925	MODELLO MODEL	00
--------------	----	-----------------------	----	--------------	-------	---------------------	-----	------------------	----